



4. One electrically driven pump capable of delivering 900 liters of water per minute at 0.3n/mm2 pressure connected to terrace tank.
5. Public address system with two ways communication facility should be provided at each floor near each staircase landing with its console at the control room, located on the ground floor.
6. Two terrace tank each of 10,000 liters capacities have been provided and connected to terrace pump.
7. Signage boards, fire safety plan & fire order are Provided.
8. Portable fire extinguishers are provided as per NBC.
9. Four persons are trained in fire prevention and firefighting at R.A.Mundkur Fire and Emergency Service Academy. Bannerughatta Road, Bangalore-560029.

Defects are not rectified Details are follows

1. The builder has not obtained any NOC / CC from the Department.
2. The height of the building is 20.20 mtrs for which the required setback of 07.00 mtrs and driveway of 6.00 mtrs on all around the building should not provided.
3. 40% of the occupants have not been trained in fire prevention and firefighting at R.A.Mundkur Fire and Emergency Service Academy, Bannerughatta Road, Bangalore-560029.

ಆದ್ದರಿಂದ ತಾವು ಈ ಬಗ್ಗೆ ಜರೂರಾಗಿ ಕ್ರಮ ಕೈಗೊಂಡು ಮೇಲಿನ ನ್ಯೂನತೆಗಳನ್ನು ಸರಿಪಡಿಸಲು ಸೂಚಿಸಲಾಗಿದೆ. ನ್ಯೂನತೆಗಳನ್ನು ಜರೂರಾಗಿ ಸರಿಪಡಿಸಿ, ವರದಿಯನ್ನು ಈ ಕಛೇರಿಗೆ ಸಲ್ಲಿಸತಕ್ಕದ್ದು ಉಲ್ಲೇಖ (1) ರಂತೆ ಕ್ರಮ ಕೈಗೊಳ್ಳಲಾಗುವುದು ಸರ್ಕಾರಿ ಅಧಿಸೂಚನೆ ಪ್ರತಿಯನ್ನು ಈ ಪತ್ರದೊಂದಿಗೆ ಲಗತ್ತಿಸಲಾಗಿದೆ.


 ಜಿಲ್ಲಾ ಅಗ್ನಿಶಾಮಕ ಅಧಿಕಾರಿ
 ಜಯನಗರ ಅಗ್ನಿಶಾಮಕ ತಾಣ
 ಎನ್.ಜಿ.ಫುಲ್ಕರಸ್ತೆ, ಬೆಂಗಳೂರು-560029


 Principal
 BANGALORE INTERNATIONAL ACADEMY (CBSE)
 Aff. No: 830159 & School Code: 45136
 32nd Cross, 7th Block, Jayanagar
 BANGALORE - 560 082


 CHAIRMAN
 BANGALORE INTERNATIONAL ACADEMY
 # 244/C, 32nd Cross 7th Block Jayanagar,
 Bangalore - 560 082.